



# Consulting Arborist Report Type 1

PO BOSTONSITE PO	NAME_ ADDRES 5 <sup>th</sup> St. 8 <sup>th</sup> an	88_ <b>236</b> New	<b>Emer</b> s		Bron		CITY	NY, N	IY	TEL#_ <b>9</b> 2	zip co			
COMPANY A 330 W. 5. Between	ADDRES 5 <sup>th</sup> St. 8 <sup>th</sup> an	88_ <b>236</b> New	<b>Emer</b> s	son Ave	Bron					TEL#_ <b>9</b> 2	29-846	-8928		
330 W. 5 Between	5 <sup>th</sup> St. 8 <sup>th</sup> an	New	York, N			k, NY						10	ACE	
Between	8 <sup>th</sup> an			ΙΥ							_ ZIP CC	DE <b>10</b>	405	
Between	8 <sup>th</sup> an													
6 /16			100					BOI	ROUGH_	Manh	attan			
		7_/_1	4 / 16											
and Wo	rk Sit	e Deta	ils (All	mitigat	ion wo	rk mu	st be o	done i	n the I	oresend	e of th	e CA)		
			<u> </u>										р	S
bh) in	æ	aue	on :10ft	"Dch	ee To nch)	epair (	epair (	epair (	vice	spair (	epair (	epair (	aduire	Other: ATTACH NOTES
ter (d	ad (F	on Zc	nensi - 5ftx	rea W'xL'3 fx36ii	om Tr rea (i	way -	ice ) – Re	) – Re	ər Ser epair	all ) – Re	) – Re	et/ ion ) – Re	ork Re ss**	H
lame	Spre	otecti 1.5ft	i.e.	tion a ions \ ftx10f	e Frotion A	Drive k ion (1	Servi ion (I	rvice ion (I	Wate ion/R	g Wa ion (I	l) noi	nicati ion (I	al Wo Park	ATT.
u k	anopy	ee Pr	ee Be	ccaval mens e 5	stanc ccaval t Clos	urb – I dewal stallat	ectric	as Se stallat	ewer - stallat	etainir stallat	ault stallat	able/Ir ommu stallat	emedi / NYC Attach	her.
16"	45'	24'			<u>ద్య€</u> " 1.5'	1 2 2 2 2	正兰	8 =	S ==	<u> </u>	» <u>=</u>	202	<u> </u>	
<u>er</u> .   16"	30'	24'	4' x 5'	3'x100'x24	1" 1.5'	I				3				
16"	35'	24'	4' x 5'	3'x100'x24	" 1.5'	I								3.5
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,														
	-													
						1 1								
	16" Lunk Diameter (dbh) inch	16" 45'  Vlocust 16" 30' rree 16" 35'	/locust 16" 35' 24' Tree Tree Protection Zone 16" 35' 24'  The Protection Zone 16" 35' 24'	Alocanst  19. 42. 74. 4. × 2. 19. 10. 10. 10. 10. 10. 10. 10. 10. 10. 10	/locrist	/locrast	Trunk Diameter (dbh) inch   Trunk Diameter (dbh) inch   Trunk Diameter (dbh) inch   16.   16.   16.   17.   16.	Trunk Diameter (dbh) inch   Trunk Diameter (dbh) inch	Trunk Diameter (dbh) inch   Trunk Diameter (dbh) inch   Trunk Diameter (dbh) inch   Trunk Diameter (dbh) inch   16.	Tree Protection Zone  19. 30. 54. 4. 7. 51. 1. 6 5fx10ft  Tree Bed Dimension  (Dbh X 1.5ft.)  Tree Bed Dimension  WXL YD'  10. 42. 57. 7. 6 5fx10ft 36inch  10. 57. 7. 7. 6 5fx10ft 36inch  10. 10. 10. 10. 10. 10. 10. 10. 10. 10.	Trunk Diameter (dbh) inch  10. 19. 19. 19. 19. 19. 19. 19. 19. 19. 19	Trunk Diameter (dbh) inch   10	16" 45' 24' 4' x 5' 3'x100'x24" 1.5'	Trunk Diameter (dbh) inch  Tarunk Diameter (dbh) inch  Tree Protection Zone  (Dbh X 1.5ft.)  Tree Bed Dimension  WXL ' i.e 5ftX10ftX36inch  I.e 5ftX10ftX36inch  AX Closest Point)  Curb - Driveway - Sidewalk Installation (I) - Repair (R)  Sewer - Water Service Installation (I) - Repair (R)  Retaining Wall Installation (I) - Repair (R)  Retaining Wall Installation (I) - Repair (R)  Remedial Work Required  By NYC Parks  **Attach Notes**

Date Revised: 1.16.2014 Page 1 of 4



### **SECTION 3- Photo Documentation**

Shown are 4'x 5' bed dimensions before curb & sidewalk work started on July 6, 2016.





Removal of 18" granite curb required excavation streetside (north) of curb ONLY, as shown. Excavation depth of 24" allowed crew to break then remove northern half of concrete footing



After broken half of footing was removed, the 12' long, 18" granite slabs simply fell northward with a pry bar. Slabs' tight fit /wedged condition and heavy weight facilitated 'dropping' of the curb. After first was pryed out, the rest fell like dominos – peeling away from tree beds and root zones, *cleanly*, in less than an hour of time. (Hats off!)

The vertical 'face, or wall of earth, behind the curb <u>was fully intact</u> after prying the curb away from it, <u>as were **all tree roots** growing vigorously right at the face, to strengthen and hold it up. Close-ups on next page.</u>









Exemplary profiles like this of intact tree roots for entire work length was unbelievable, but amazing to see. An accomplishment, by any measure.

This is sheer vertical soil 'face' left standing after granite slabs dropped away. Note the hefty roots descending from trunk of **Tree 1** Honeylocust.

#### REPRESENTATIVE CLOSE-UPS OF 100' LENGTH EXCAVATION

With these **zero**-impact results documented, HLA CA questions **why** 'drop' removal procedure by contractor here isn't spelled out more? Does *anyone* know?

<u>What's not in question?</u> A sure means to keep most, if not all, street tree roots intact is to pry away and 'drop' curbs in the course of removing them, especially when maximum root preservation is critical for saving a tree.

Bed 3





MITIGATION
Bed areas expanded to 5' x 10'.

Bed 3 expanded westward only, according to property line and owner limit of responsibility.

Date Revised: 1.16.2014 Page **3** of **4** 

# Consulting Arborist Report Type 1



## **Signature Certification**

I hereby certify that I have presented an accurate and truthful representation of the work conducted at the location described herein. I have worked to ensure compliance with all accepted professional standards in arboricultural practices and to ensure compliance with all applicable laws, regulations, policies and ethical standards. In the event the contractor has failed to comply with all applicable laws, regulations, policies and ethical standards; or created conditions that may present a hazard to people or property, I have immediately notified the appropriate representative of New York City Department of Parks and Recreation.									
X While I. Reggies	ISA Certification#	NY-5409A 							
DO NOT WRITE BELOW THIS LINE: FOR NYCDPR USE ONLY									
NYC PARKS OFFICE USE ONLY:									
CONSULTING ARBORIST REPORT   APPROVED	☐ REJECTED	DATE:							
NYC DPR EMPLOYEE NAME	TITLE								

Date Revised: 1.16.2014 Page 4 of 4